01-Jan-26	DAILY MAINTENANCE REPORT										
S/N	Asset Code	Description	Date of B/D	BD Days	Location	Breakdown Reason	Components	Technicians	Duration	Status	Maintained
		Tipper: 5									
1	321 39 130	Tata-10 wheeler	1-Jan-26	2	WORKSHOP	Comprehensive system inspection and servicing performed in accordance with maintenance protocols	Engine Oil, Fuel filter	Mandip, Bimal	5 hrs	Completed	30-Dec-25
2	321 39 110	Eicher-10 wheeler	1-Jan-26	2	WORKSHOP	Hydraulic piping system inspected; leakage points sealed and system restored		Arjun, Sushil	1 hr	Completed	29-Dec-25
3	321 39 139	Eicher-10 wheeler	1-Jan-26	2	WORKSHOP	Exhaust silencer flexible pipe repaired and reinstalled; tyre defect attended and resolved; greasing completed	Flex pipe, Grease	Arjun, Bimal, Kedar	2.5 hrs	Completed	19-Dec-25
4	321 39 107	Eicher-10 wheeler	1-Jan-26	2	WORKSHOP	Defective hydraulic pipe repaired, eliminating oil seepage,preliminary inspections completed		Alek, Manish	1 hr	Completed	30-Dec-25
5	321 39 97	Eicher-10 wheeler	1-Jan-26	2	WORKSHOP	Steering Oil replenished	Steering oil	Arjun, Sushil	30 min	Completed	31-Dec-25
		Camper: 1									
6	BA19CHA6047	TOYOTA HILUX	1-Jan-26	2	WORKSHOP	Wheel–tyre assemblies interchanged in accordance with manufacturer-recommended rotation sequence; noise issue attended		Sagar	1 hr	Completed	28-Dec-25
		DG: 1									
7	320 07 60	CAT 500 KVA Generator	1-Jan-26	2	TRT	End-to-end servicing performed as per schedule	Engine Oil, Fuel filters, Air Filter, Lubricating oil	Alek, Sagar, Arjun, Mandip	1.5 hrs	Completed	12-Dec-25

02-Jan-26	DAILY MAINTENANCE REPORT										
S/N	Asset Code	Description	Date of B/D	BD Days	Location	Breakdown Reason	Components	Technicians	Duration	Status	Maintained
		Tipper: 3									
1	321 39 130	Tata-10 wheeler	2-Jan-26	1	WORKSHOP	No engine pickup noted due to electrical wiring issue even after servicing resolved, RR buggy lock manufactured and welded		Ram, Anil, Dipak	2 hrs	Completed	1-Jan-25
2	321 39 139	Eicher-10 wheeler	2-Jan-26	1	WORKSHOP	Bent stabilizer rod assembly rectified by straightening		Sushil, Arjn, Mandip	45 min	Completed	1-Jan-25
3	321 39 111	Eicher-6 wheeler	2-Jan-26	1	WORKSHOP	Lubrication applied to all pivot joints, linkages, and fittings		Biman	15 min	Completed	31-Dec-25
		Camper: 2									
4	BA19CHA6047	TOYOTA HILUX	2-Jan-26	1	WORKSHOP	Worn brake pads removed and new pads installed as per specifications	Brake pad	Sagar	1 hr	Completed	28-Dec-25
5	341 03 40	Mahindra Bolero	2-Jan-26	1	WORKSHOP	Hydraulic tank leakage arrested; tank hose pipe found defective and requires replacement.; starting issue attended	Resibond	Mandip, Bimal, Binod, Ram, Arjun	1 hr	Completed	28-Dec-25
		DG: 1									
6	321 07 61	CAT 500 KVA Generator	2-Jan-26	1	MAT	End-to-end servicing performed as per schedule	Engine Oil, Fuel filters, Air Filter, Lubricating oil	Kedar, Arjun	1 hr	Completed	-
		Backhoe: 2									
7	321 44 49	Backhoe-JCB	2-Jan-26	1	WORKSHOP	Lubricants applied to all pivot assemblies, linkages, and fittings	Grease	Binod	25 min	Completed	29-Dec-25
8	321 44 40	Backhoe-Bull	2-Jan-26	1	WORKSHOP	Comprehensive lubrication of mechanical and moving components completed	Grease	Binod	25 min	Completed	26-Dec-25
		Air compressor: 1									
9	321 03 68	AIR COMPRESSOR(XAS 400-100)	2-Jan-26	1	WORKSHOP	hose reinforced by welding and made operational	Electrodes	Anil, Bhim, Dipak	1 hr	Completed	23-Dec-25
		Wheel Loader: 1									
10	321 44 51	Lonking Wheel Loader	2-Jan-26	1	WORKSHOP	Tyre pressure checked and refilled to specified levels		Bimal	15 min	Completed	-
		Mobil Crane: 1									
11	321 43 18	Truck Mount Crane(Zoomlin)	2-Jan-26	1	WORKSHOP	FR bumper repaired by welding, alignment checked, and installed back		Dipak	1 hr	Completed	-
		Excavator: 4									
12	321 45 45	CAT Excavator 323D3	2-Jan-26	1	THEEWA	Sim replacement carried out	Shims	Kedar, Sagar	20 min	Completed	-
13	321 45 39	Kobelco Excavator SK220	2-Jan-26	1	SISNEY VIR	Hydraulic hose leakage in rock hammer breaker attended; hose and fittings replaced with new; breaker bolts issue resolved; 2 jobs in different time frames	Hose, fittings	Alek, Sagar, Binod, Kedar, Arjun	2 hrs	Completed	30-Dec-25
14	321 45 38	Komatsu Excavator PC-210	2-Jan-26	1	SURGESHAFT	Lubricants applied to all pivot assemblies, linkages, and fittings	Grease	Sagar, Binod	30 min	Completed	29-Dec-25
15	321 45 21	Komatsu Excavator PC-210	2-Jan-26	1	0 KILO	Bucket teeth and locking mechanisms replaced	Grease	Sagar, Binod	30 min	Completed	29-Dec-25

03-Jan-26	DAILY MAINTENANCE REPORT										
S/N	**Asset Code**	**Description**	**Date of B/D**	**BD Days**	**Location**	**Breakdown Reason**	**Components**	**Technicians**	**Duration**	**Status**	**Maintained**
		Tipper: 4									
1	321 39 124	Eicher-10 wheeler	3-Jan-26	0	WORKSHOP	FR RH leaf spring replacement carried out. brackets repaired	leaf springs, u-bolts	Arjun, Mandip, Sushil, Bimal	3 hrs	Completed	29-Dec-25
2	321 39 103	Lowbed	3-Jan-26	0	WORKSHOP	RR leaf springs changed; electrical circuits inspected and repaired		Mandip, Bimal, Ram	4 hrs	Completed	24-Dec-25
3	321 39 130	Tata-10 wheeler	3-Jan-26	0	TAPETHOK	Propeller shaft coupling unit needs replacement	Repaired Salvaged Coupling	Arjun, Alek	5 hrs	Completed	2-Jan-26
4	321 39 110	Eicher-10 wheeler	3-Jan-26	0	ZERO KILO	Tie rod issue; unit needs replacement; under maintenance	Repaired Salvaged Tie rod end	Bimal,Mandip, Manish	3 hrs	Pending	1-Jan-26
		Camper: 1									
5	341 03 40	Mahindra Bolero	3-Jan-26	0	WORKSHOP	Light indicator control switch fault attended to and rectified		Ram	1.5 hrs	Completed	2-Jan-26
		Backhoe: 1									
6	321 44 40	Backhoe-Bull	3-Jan-26	0	WORKSHOP	Bucket teeth bolts inspected and properly tightened		Kedar	25 min	Completed	2-Jan-26
		Wheel Loader: 1									
7	321 44 45	Wheel Loader-Lonking	3-Jan-26	0	WORKSHOP	Bucket teeths and locks, adaptor changed	Teeths & Pins, Electrodes	Anil, Dipak	50 min	Completed	29-Dec-25
		Excavator: 4									
8	321 45 40	CAT Excavator 323D3	3-Jan-26	0	0 KILO	Routine maintenance completed as scheduled	Engine Oil, Oil filter, Fuel filters, Air Filter, Grease	Kedar, Sagar, Binod	4 hrs	Completed	29-Dec-25
9	321 45 41	CAT Excavator 323D3	3-Jan-26	0	0 KILO	Planned maintenance carried out				Completed	28-Dec-25
10	321 45 42	CAT Excavator 323D3	3-Jan-26	0	0 KILO	Scheduled service executed successfully.				Completed	28-Dec-25
11	321 45 44	CAT Excavator 323D3	3-Jan-26	0	0 KILO	Scheduled servicing attended to and completed				Completed	26-Dec-25
		Air Compressor: 1									
12	321 03 71	Air Compressor XAS 550-100	3-Jan-26	0	TAWA	Issue with wheel mountings attended; to be repaired in initial hours		Kedar, Sagar	1.5 hrs	Pending	2-Jan-26

04-Jan-26	DAILY MAINTENANCE REPORT										
S/N	Asset Code	Description	Date of B/D	BD Days	Location	Breakdown Reason	Components	Technicians	Duration	Status	Maintained
Tipper: 5											
1	321 39 110	Eicher-10 wheeler	3-Jan-26	13	WORKSHOP	Tie rod issue; unit needs replacement; maintenance completed	Repaired Salvaged Tie rod end	Bimal,Mandip, Manish,Dipak,Anil	30 min	Completed	1-Jan-26
2	321 39 114	Eicher-10 wheeler	4-Jan-26	12	WORKSHOP	Project Phoenix- Accident-affected unit moved to workshop and taken up for maintenance		Arjun, Balmukunda		Pending	-
3	321 39 135	Eicher-10 wheeler	4-Jan-26	12	WORKSHOP	Lubricants applied to all pivot assemblies, linkages, and fittings; Vacuum pipe diagphram T-pipe changed;PWDO regulator unit needs replacement	Grease; T-hose pipe	Arjun, Binod	1.5 hrs	Completed	29-Dec-25
4	321 39 133	Tata-10 wheeler	4-Jan-26	12	WORKSHOP	Tyre puncture attended and rectified; vacuum switch malfunction resolved; headlamp wiring fault identified, repaired, and functionality restored.		Manish, Ram	2.5 hrs	Completed	18-Dec-25
5	321 39 97	Eicher-10 wheeler	4-Jan-26	12	WORKSHOP	Radiator hose pipe issue resolved		Arjun	30 min	Completed	1-Jan-26
Camper: 3											
6	341 03 40	Mahindra Bolero	4-Jan-26	12	SURGESHAFT	Control switch electrical wiring issue attended, Greased	15A fuse, grease	Ram, Alek	2 hrs	Completed	3-Jan-26
7	321 44 38	Mahindra Bolero	4-Jan-26	12	WORKSHOP	Front leaf springs, crown oil seal replaced; rear tank cover welding completed; radiator issue identified and rectified, restoring normal operation.	Leaf spring, u bolts, oil seal, Electrodes, Coolant	Mandip, Manish	4 hrs	Completed	3-Jan-26
8	321 44 30	Mahindra Bolero	4-Jan-26	12	WORKSHOP	Rear body frame welding repair carried out; shackle assembly fasteners (washers, nuts, and bolts) replaced and secured.	Electrodes, Shackle nuts & bolts	Sagar, Bimal, Anil	20 min	Completed	30-Dec-25
Excavator: 3											
9	321 45 21	Komatsu Excavator PC-210	4-Jan-26	12	ZERO KILO	Hydraulic pipe line sleepage issue resolved; SAE 46 Hydraulic Oil replenished by 20 L	Oring, Hydraulic oil	Kedar, Arjun	50 min	Completed	2-Jan-26
10	321 45 16	Excavator 360 (Hyundai)	4-Jan-26	12	CRUSHER	Chain track plate fasteners (bolts and nuts) checked and securely torqued as per specification		Kedar	30 min	Completed	29-Dec-25
11	321 45 44	CAT Excavator 323D3	4-Jan-26	12	SHIWA	Bucket teeth pins changed	Lock pins	Manish	10 min	Completed	3-Jan-26
Grader: 1											
12		HIDROMEK MG 430	4-Jan-26	12	WORKSHOP	Comprehensive lubrication of mechanical and moving components completed; Hydraulic oil replenished by 15L	Grease, Hydraulic Oil	Alek, Sagar, Arjun, Mandip	2 hrs	Completed	31-Dec-25
Roller: 1											
13	321 46 04	Dynapac Roller	4-Jan-26	12	WORKSHOP	Air filter cleaned; pick up issue attended		Ram, Sagar	1 hr	Completed	23-Dec-25

05-Jan-26	DAILY MAINTENANCE REPORT										
S/N	Asset Code	Description	Date of B/D	BD Days	Location	Breakdown Reason	Components	Technicians	Duration	Status	Maintained
Tipper: 4											
1	321 39 114	Eicher-10 wheeler	4-Jan-26	12	WORKSHOP	Three tyres repaired and mounted; required in-stock components assembled		Balmukunda, Sagar, Binod, Manish, Mandip		Pending	-
2	321 39 93	Eicher-6 wheeler	5-Jan-26	11	WORKSHOP	Radiator under repair; unit needs immediate replacement		Alek, Manish, Mandip		Pending	2-Jan-26
3	321 39 110	Eicher-10 wheeler	5-Jan-26	11	SHIWA	Tyre puncture attended and rectified; tyre refitted after ensuring air pressure compliance	Repaired Tyre	Alek, Manish, Mandip	1.5 hrs	Completed	3-Jan-26
4	321 39 139	Eicher-10 wheeler	5-Jan-26	11	WORKSHOP	New tyre replaced	Tyre SN (V02428K25)	Sagar, Manish	15 min	Completed	25-Dec-25
Excavator: 3											
5	321 45 25	Excavator 360 (Hyundai)	4-Jan-26	12	WORKSHOP	Bucket currently undergoing repair and reconditioning	Electrodes	Anil, Bhim, Dipak		Pending	24-Dec-25
6	321 45 44	CAT Excavator 323D3	5-Jan-26	11	SHIWA	Worn bucket removed and new bucket installed & lubrication carried out as per maintenance standards	Bucket, Grease	Kedar, Sagar, Binod	25 min	Completed	4-Jan-26
7	321 45 16	Excavator 360 (Hyundai)	5-Jan-26	11	CRUSHER	Issue when attended found bucket teeth locks to replace; parts out of stock		Alek	5 min	Completed	4-Jan-26
8	321 45 21	Komatsu Excavator PC-210	4-Jan-26	12	THAUWA	Windshield assembly fittings restored to serviceable condition	Silicon paste	Kedar, Manish, Mandip	30 min	Completed	4-Jan-26
Air Compressor: 1											
9	321 03 62	Air Compressor (XAS 187)	5-Jan-26	11	WORKSHOP	Housing repaired by remanufacturing and welding; structural integrity restored		Bhim, Dipak, Anil	1 hr	Completed	14-Dec-25
Tractor: 1											
10	321 38 32	Mahindra Tractor	5-Jan-26	11	WORKSHOP	Tyre puncture repaired; RR buggy lock welded and repaired.	Tyre SN (D053160525) Electrodes	Alek, Sagar, Binod, Anil	2 hrs	Completed	-

06-Jan-26	DAILY MAINTENANCE REPORT										
S/N	**Asset Code**	**Description**	**Date of B/D**	**BD Days**	**Location**	**Breakdown Reason**	**Components**	**Technicians**	**Duration**	**Status**	**Maintained**
		Tipper: 6									
1	321 39 93	Eicher-6 wheeler	5-Jan-26	11	WORKSHOP	Radiator under repair; unit needs immediate replacement		Ram, Alek, Manish, Mandip	3 hrs	Completed	2-Jan-26
2	321 39 130	Tata-10 wheeler	6-Jan-26	10	WORKSHOP	RR buggy lock welded and repaired; Ribbed V belt issue; procured parts mismatched; unit needs replacement	Electrodes	Sagar, Binod, Anil, Dipak	2 hrs	Completed	3-Jan-26
3	321 39 133	Tata-10 wheeler	6-Jan-26	10	WORKSHOP	New tyre replaced and greased	Grease, Tyre	Binod, Manish	1.5 hrs	Completed	4-Jan-26
4	321 39 156	TATA BULKER	6-Jan-26	10	WORKSHOP	Worn U-bolts and center bolt were replaced, and defective wiper blades were renewed	U bolt, center bolt, Wiper blade	Balmukunda, Sagar, Mandip, Ram	2.5 hrs	Completed	-
5	321 39 107	Eicher-10 wheeler	6-Jan-26	10	WORKSHOP	Tyre puncture repaired; remaining initial hours		Manish, Mandip	1.5 hrs	Pending	1-Jan-26
6	321 39 134	Eicher-10 wheeler	6-Jan-26	10	WORKSHOP	Tyre puncture repaired; under maintenance		Manish, Mandip	1 hr	Pending	4-Jan-26
		Camper: 4									
7	LUPR01001CHA3504	Mahindra Bolero	6-Jan-26	10	WORKSHOP	All joints, linkages, and mechanical fittings greased	Grease	Binod	15 min	Completed	31-Dec-25
8	BAPR01031CHA7849	MAHINDRA BOLERO	6-Jan-26	10	WORKSHOP	Component greased; operation checked and found satisfactory	Grease	Binod	15 min	Completed	18-Dec-25
9	GA4CHA1930	MAHINDRA BOLERO	6-Jan-26	10	WORKSHOP	Greasing performed on all serviceable points.	Grease	Binod	15 min	Completed	14-Dec-25
10	321 44 30	Mahindra Bolero	6-Jan-26	10	WORKSHOP	Starting issue attended	Grease	Ram, Kedar	20 min	Completed	4-Jan-26
		Tractor: 1									
11	ME1TA7195	Hired- Tractor-Local	6-Jan-26	10	WORKSHOP	Lubricants applied to all pivot assemblies, linkages, and fittings	Grease	Binod	15 min	Completed	6-Dec-25
		Transit Mixture: 1									
12	321 39 152	TATA putzmeister Mixture	6-Jan-26	10	WORKSHOP	Rear suspension mounting points: all nuts and bolts tightened and secured		Manish, Alek	1.5 hrs	Completed	24-Dec-25
		Excavator: 4									
13	321 45 19	Komatsu Excavator PC-210	29-Dec-25	18	MITLUNG	All joints, linkages, and mechanical fittings greased	Grease	Kedar, Binod	20 min	Completed	25-Dec-25
14	321 45 39	Kobelco Excavator SK220	2-Jan-26	14	SISNEY VIR	Greasing performed on all serviceable points.	Grease	Kedar, Binod	20 min	Completed	30-Dec-25
15	321 45 38	Komatsu Excavator PC-210	6-Jan-26	10	THAUWA	Boom cylinder pipe bolts tightened and greased	Grease	Kedar, Binod	40 min	Completed	2-Jan-26
16	321 45 21	Komatsu Excavator PC-210	6-Jan-26	10	THAUWA	Lubricants applied to all pivot assemblies, linkages, and fittings	Grease	Kedar, Binod	30 min	Completed	5-Jan-26

07-Jan-26	DAILY MAINTENANCE REPORT										
S/N	Asset Code	Description	Date of B/D	BD Days	Location	Breakdown Reason	Components	Technicians	Duration	Status	Maintained
Tipper: 7											
1	321 39 107	Eicher-10 wheeler	6-Jan-26	10	WORKSHOP	Multiple tyres were renewed, and the windshield frame was repaired, aligned, and greased	Tyre SN (D148493425/V064 524125), Grease	Manish, Mandip, Sagar	1.5 hrs	Completed	1-Jan-26
2	321 39 134	Eicher-10 wheeler	6-Jan-26	10	WORKSHOP	Tyre puncture was identified and repaired, ensuring proper air retention, and greased to restore smooth operation.	Electrodes, Grease	Manish, Mandip	1.5 hrs	Completed	4-Jan-26
3	321 39 124	Eicher-10 wheeler	7-Jan-26	9	WORKSHOP	Wheel rotation obstruction caused by a lodged stone was cleared, restoring normal tyre movement		Mandip, Manish	30 min	Completed	3-Jan-26
4	321 39 97	Eicher-10 wheeler	7-Jan-26	9	WORKSHOP	Gear lock malfunction was addressed, and the affected components were welded and repaired to restore normal operation.	Electrodes	Sagar, Ram, Mandip, Dipak	1.5 hrs	Completed	4-Jan-26
5	321 39 140	Tata- Lowbed	7-Jan-26	9	WORKSHOP	All support parts nuts and bolts tightended and greased	Grease	Binod	20 min	Completed	31-Dec-25
6	321 39 125	Mini Truck SML (4 Wheeler)	7-Jan-26	9	WORKSHOP	Replacement of the main spring mounting was carried out, followed by renewal of gear oil and lubrication of the wheel hub assembly; top srping unit needs immediate replacement	FR Mounting, Electrodes, Gear Oil, Grease	Alek, Manish, Mandip, Sagar	4.5 hrs	Pending	15-Dec-25
7	321 39 110	Eicher-10 wheeler	7-Jan-26	9	WORKSHOP	Tyre logged with foreign element rectified		Binod, Mandip	15 min	Completed	5-Jan-26
Camper: 1											
8	341 03 40	Mahindra Bolero	7-Jan-26	9	WORKSHOP	Greasing performed on all serviceable points.	Grease	Ram, Alek	15 min	Completed	4-Jan-26
Backhoe: 1											
9	321 44 49	Backhoe-JCB	7-Jan-26	9	WORKSHOP	Lubricants applied to all pivot assemblies, linkages, and fittings, Tyre pressure check	Grease	Binod	25 min	Completed	2-Jan-26
Transit Mixture: 2											
10	321 39 152	TATA putzmeister Mixture	7-Jan-26	9	WORKSHOP	All mounting nuts and bolts were replaced with new fasteners to ensure secure assembly	Bolts and nuts	Manish, Alek	1.5 hrs	Completed	6-Jan-26
11	321 39 143	TATA putzmeister Mixture	7-Jan-26	9	WORKSHOP	All support parts nuts and bolts tightended and greased	Grease	Alek, Manish	1 hr	Completed	-
Air Compressor: 1											
12	321 03 62	Air Compressor (XAS 187)	7-Jan-26	9	SURGESHAFT	Starting malfunction was identified, attended, and resolved, restoring normal engine start-up.		Kedar	30 min	Completed	14-Dec-25
Excavator: 4											
13	321 45 25	Excavator 360 (Hyundai)	4-Jan-26	12	WORKSHOP	Repaired bucket assembly refabricated and will be installed tomorrow	Repaired Bucket, Shim	Kedar, Sagar, Binod	20 min	Completed	24-Dec-25
14	321 45 41	CAT Excavator 323D3	25-Dec-25	22	THAUWA	Windshield protector fabricated and installed	Electrodes, rods	Bhim, Dipak	3 hrs	Completed	20-Dec-25

08-Jan-26	DAILY MAINTENANCE REPORT										
S/N	Asset Code	Description	Date of B/D	BD Days	Location	Breakdown Reason	Components	Technicians	Duration	Status	Maintained
Tipper: 1											
1	321 39 103	Lowbed	8-Jan-26	8	WORKSHOP	Multiple tyre puncture repaired; Excessive free play observed in the steering mechanism resolved; parts welded and repaired		Mandip, Ram, Balmukunda	3 hrs	Completed	3-Jan-26
Excavator: 2											
2	321 45 42	CAT Excavator 323D3	8-Jan-26	8	0 KILO	Nitrogen gas charged in rock breaker accumulator (back head gas chamber) as per specification and greased	Grease	Kedar, Sagar, Binod	35 min	Completed	3-Jan-26
3	321 45 39	Kobelco Excavator SK220	8-Jan-26	8	SISNEY VIR	Greasing performed on all serviceable points.	Grease	Kedar, Sagar, Binod	20 min	Completed	2-Jan-26

09-Jan-26	DAILY MAINTENANCE REPORT										
S/N	Asset Code	Description	Date of B/D	BD Days	Location	Breakdown Reason	Components	Technicians	Duration	Status	Maintained
		Tipper: 6									
1	321 39 114	Eicher-10 wheeler	4-Jan-26	12	WORKSHOP	Clutch set changed, pilot bearing changed, Cabin struts changed, Actuator MTG Bkts changed; waiting for P.R. No:714	Clutch set, release bearing,cabin struts assy, actuator bkts	Bahmukunda, Sagar, Arjun, Kedar	5 hrs	Pending	-
2	321 39 134	Eicher-10 wheeler	9-Jan-26	7	WORKSHOP	Starting issue attended		Ram, Alek	30 min	Completed	6-Jan-26
3	321 39 110	Eicher-10 wheeler	9-Jan-26	7	WORKSHOP	Filter air cleaner issue resolved		Binod	15 min	Completed	7-Jan-26
4	321 39 124	Eicher-10 wheeler	9-Jan-26	7	WORKSHOP	Starter Assy replaced; Dynamo replaced from ACDT vehicle, Brakes adjusted	Repaired Self, Salvaged Dynamo	Sagar, Ram	4 hrs	Completed	7-Jan-26
5	321 39 130	Tata-10 wheeler	9-Jan-26	7	WORKSHOP	FR coupling issue resolved		Alek, Arjun	30 min	Completed	6-Jan-26
6	321 39 125	Mini Truck SML (4 Wheeler)	9-Jan-26	7	WORKSHOP	Starting issue attended; Repaired main spring mounted; waiting for the placed order P.R. No:691 & 713		Bahmukunda, Ram, Alek	3 hrs	Completed	7-Jan-26
		Excavator: 4									
7	321 45 16	Excavator 360 (Hyundai)	9-Jan-26	7	SISNE VIR	Mobil & gear oil replenished by 5 and 3L resp.	Engine Oil, Gear Oil	Kedar, Binod	20 min	Completed	5-Jan-26
8	321 45 41	CAT Excavator 323D3	9-Jan-26	7	SURGE SHAFT	Lubricated all joints	Grease	Kedar, Binod	25 min	Completed	3-Jan-26
9	321 45 38	Komatsu Excavator PC-210	9-Jan-26	7	SURGE SHAFT	Lubricants applied to all pivot assemblies, linkages, and fittings	Grease	Kedar, Binod	30 min	Completed	6-Jan-26
10	321 45 21	Komatsu Excavator PC-210	9-Jan-26	7	SURGE SHAFT	Comprehensive lubrication of all moving components completed	Grease	Kedar, Binod	30 min	Completed	6-Jan-26
		Camper: 1									
11	321 44 38	Mahindra Bolero	9-Jan-26	7	TRT	Starting issue resolved		Ram	15 min	Completed	4-Jan-26

10-Jan-26	DAILY MAINTENANCE REPORT										
S/N	**Asset Code**	**Description**	**Date of B/D**	**BD Days**	**Location**	**Breakdown Reason**	**Components**	**Technicians**	**Duration**	**Status**	**Maintained**
Tipper: 6											
1	321 39 107	Eicher-10 wheeler	10-Jan-26	6	WORKSHOP	Brake unit valve issue resolved		Balmukunda, Arjun	5 hrs	Completed	6-Jan-26
2	321 39 124	Eicher-10 wheeler	10-Jan-26	6	WORKSHOP	Dynamo replaced from (321 39 86) vehicle; damaged ones to be sent for repair		Ram, Sagar	1 hr	Completed	9-Jan-26
3	321 39 135	Eicher-10 wheeler	10-Jan-26	6	WORKSHOP	Rear buggy lock fabricated and installed	Electrodes	Bhim, Anil	1 hr	Completed	4-Jan-26
4	321 39 110	Eicher-10 wheeler	10-Jan-26	6	WORKSHOP	Brakes adjusted, carry under parts welded and repaired	Electrodes	Mandip,Bhim, Anil	2.5 hrs	Completed	9-Jan-26
5	321 39 97	Eicher-10 wheeler	10-Jan-26	6	WORKSHOP	Steering pump changed	Salvaged and repaired steering pump	Sagar, Mandip, Arjun	1.5 hrs	Completed	7-Jan-26
6	321 39 140	Tata- Lowbed	10-Jan-26	6	WORKSHOP	All support parts welded, Fr seats adjusted and repaired	Electrodes	Bhim, Anil	40 min	Completed	7-Jan-26
Excavator: 1											
7	321 45 43	CAT Excavator 323D3	10-Jan-26	6	KHOKSE	Scheduled preventive maintenance completed	Engine Oil, Oil/fuel filter	Alek	1 hr	Completed	25-Dec-25
Light vehicle: 2											
8	321 44 30	Mahindra Bolero	10-Jan-26	6	WORKSHOP	Fuel pump issue; to be sent for repair		Alek, Mandip	20 min	Pending	6-Jan-26
9		Scorpio	10-Jan-26	6	WORKSHOP	Punctured tyre repaired		Alek, Mandip	45 min	Completed	-
Backhoe: 2											
10	321 44 49	Backhoe-JCB	10-Jan-26	6	WORKSHOP	Periodic servicing carried out; Bucket undermaintenance; final touch up in initial hours	Engine Oil, Oil/fuel/air/hydraulic filter, Electrodes	Sagar, Binod, Bhim, Anil	6 hrs	Completed	7-Jan-26
11	321 44 40	Backhoe-Bull	10-Jan-26	6	WORKSHOP	Bucket repaired and greased	Electrodes, grease	,Anil, Binod	2 hrs	Completed	3-Jan-26
Generator: 1											
12	321 07 53	KILOSKER GENERATOR	10-Jan-26	6	SURGESHAFT	Scheduled servicing carried out as per OEM maintenance schedule	Engine oil,lubricating oil filter, fuel filters, air cleaner element	Kedar, Arjun	2.5 hrs	Completed	3-Jan-26

11-Jan-26	DAILY MAINTENANCE REPORT										
S/N	Asset Code	Description	Date of B/D	BD Days	Location	Breakdown Reason	Components	Technicians	Duration	Status	Maintained
Tipper: 6											
1	321 39 107	Eicher-10 wheeler	10-Jan-26	6	WORKSHOP	Brake unit valve was attended and rectified earlier; however, as the concern persisted, the unit was re-serviced and recalibrated for makeshift solution; still waiting for the parts arrival		Balmukunda, Ram	5 hrs	Completed	6-Jan-26
2	321 39 124	Eicher-10 wheeler	11-Jan-26	5	WORKSHOP	Seized brake chambers, air system issues-valve malfunction; resolved by overhauling the brake mechanism, servicing the air system		Balmukunda, Mandip	2 hrs	Completed	10-Jan-26
3	321 39 103	Lowbed	11-Jan-26	5	WORKSHOP	Electrical circuit issues attended		Ram, Arjun	30 min	Completed	8-Jan-26
4	321 39 133	Tata-10 wheeler	11-Jan-26	5	WORKSHOP	Tyre puncture issue resolved by replacing repaired tyre; vacuum switch wiring resolved	Repaired Tyre	Arjun, Mandip Ram	2.5 hrs	Completed	6-Jan-26
5	321 39 138	Eicher-10 wheeler	11-Jan-26	0	WORKSHOP	Clutch set malfunction observed: silencer mounting brackets found defective		Sagar, Binod	2 hrs	Pending	8-Dec-25
6	321 39 125	Mini Truck SML (4 Wheeler)	11-Jan-26	5	WORKSHOP	Main leaf spring changed. U bolts fabricated and installed, Gear box issue shifted back to workshop; waiting for parts arrival	Top Leaf srping	Balmukunda, Mandip	2.5 hrs	Pending	9-Jan-26
Excavator: 3											
7	321 45 41	CAT Excavator 323D3	11-Jan-26	5	WORKSHOP	Front windshield frame structurally reinforced by welding and refitted, bucket shims renewed and greased	Electrodes Grease	Bhim, Anil Kedar, Binod	2 hrs	Completed	9-Jan-26
8	321 45 19	Komatsu Excavator PC-210	11-Jan-26	5	MITLUNG	Bucket teeths and locks replaced	Teeth and pins	Sagar	15 min	Completed	29-Dec-25
9	321 45 42	CAT Excavator 323D3	11-Jan-26	5	0 KILO	Rock breaker hammer damaged control valve. issues with accumulator diaphragm,worn internal seals. couldn't be repaired hence shifted to workshop		Kedar, Arjun	3.5 hrs	Pending	8-Jan-26
Shotcrete Machine: 1											
10	321 19 75	Robert Shotcrete-Putzmeister	11-Jan-26	5	TRT	Hydraulic Oil replenished; tested by service engineer for overally perfromance	Hydraulic Oil	Kedar, Sagar, Priyaram	3 hrs	Completed	31-Dec-25

12-Jan-26	DAILY MAINTENANCE REPORT										
S/N	Asset Code	Description	Date of B/D	BD Days	Location	Breakdown Reason	Components	Technicians	Duration	Status	Maintained
Tipper: 1											
1	321 39 107	Eicher-10 wheeler	10-Jan-26	6	WORKSHOP	Brake unit valve was attended and rectified earlier, however, as the concern persisted, the unit was re-serviced and recalibrated for makeshift solution; still waiting for the parts arrival; overhauled the brake mechanism with servicing the air system, suspensions tightened		Balmukunda, Sagar	4.5 hrs	Completed	6-Jan-26
Excavator: 4											
2	321 45 19	Komatsu Excavator PC-210	12-Jan-26	4	0 KILO	Defective radiator hose leakage repaired restoring cooling system integrity		Ram, Alek	2.5 hrs	Completed	11-Jan-26
3	321 45 21	Komatsu Excavator PC-210	12-Jan-26	4	0 KILO	Hydraulic pipeline leakage resolved	Sleeve fittings	Arjun, Alek, Anil	1 hr	Completed	9-Jan-26
4	321 45 40	CAT Excavator 323D3	12-Jan-26	4	KHOKSE	Boom cylinder replaced with old unit	Salvaged cylinder	Kedar, Bmod	3 hrs	Completed	3-Jan-26
5	321 45 42	CAT Excavator 323D3	11-Jan-26	5	0 KILO	Rock breaker hammer damaged control valve, issues with accumulator diaphragm worn internal seals repaired and installed back, still issues thus shifted to workshop		Arjun, Alek	2.5 hrs	Pending	8-Jan-26
Transit Mixture: 1											
6	320 39 108	T M CONMAT	12-Jan-26	4	WORKSHOP	Hopper pillow block bearing support brackets repaired through welding and installed back in position	Electrodes	Balmukund, Sagar, Anil, Bhim	2.5 hrs	Completed	25-Dec-25
Tractor: 1											
7	ME11A7195	Hired- Tractor-Loca.	12-Jan-26	4	WORKSHOP	Support brackets welded and reinforced	Electrodes	Bhim, Anil	50 min	Completed	6-Jan-26

13-Jan-26	DAILY MAINTENANCE REPORT										
S/N	Asset Code	Description	Date of B/D	BD Days	Location	Breakdown Reason	Components	Technicians	Duration	Status	Maintained
Tipper: 4											
1	321 39 130	Tata-10 wheeler	13-Jan-26	3	WORKSHOP	Starting malfunction rectified; starter assembly solenoid replaced with a serviceable salvaged unit and reinstalled	Salvaged Solenoid	Ram	1 hr	Completed	9-Jan-26
2	321 39 97	Eicher-10 wheeler	13-Jan-26	3	WORKSHOP	Defective diaphragm unit replaced with a serviceable salvaged unit; system restored	Salvaged Diaphragm	Arjun, Alex	1.5 hrs	Completed	10-Jan-26
3	321 39 133	Tata-10 wheeler	13-Jan-26	3	WORKSHOP	Brakes adjusted		Alek	15 min	Completed	11-Jan-26
4	321 39 125	Mini Truck SML (4 Wheeler)	11-Jan-26	5	WORKSHOP	Gear box overhauled to place the order		Sagar, Binod	2.5 hrs	Pending	9-Jan-26
Excavator: 3											
5	321 45 39	Kobelco Excavator SK220	8-Jan-26	8	SHIWA	Hydraulic oil replenished	Hydraulic Oil	Sagar, Binod	1 hr	Completed	2-Jan-26
6	321 45 40	CAT Excavator 323D3	13-Jan-26	3	WORKSHOP	Bucket repaired	Electrodes	Bhim, Anil	3 hrs	Completed	12-Jan-26
7	321 45 38	Komatsu Excavator PC-210	9-Jan-26	7	SURGE SHAFT	Hydraulic & breaker oil filters serviced and greased	Hydraulic filter, breaker filter, Grease	Sagar, Binod	2 hrs	Completed	6-Jan-26
Rock Hammer Breaker: 1											
8	321 17 04	Breaker hammer	13-Jan-26	3	WORKSHOP	Seal kits replaced and collar bush yet to be replaced. The seized collar bush could not be removed by conventional methods. therefore, controlled gas cutting was carried out to extract the old bush	Seal kit, Color bush, Electrodes	Kedar, Bahuktauda Ram,Anil	9.5 hrs	Pending	-
Tractor: 2											
9	321 38 30	Tractor Newholland	13-Jan-26	3	WORKSHOP	Starter system issue rectified; normal operation restored		Ram, Alek	30 min	Completed	-
10	321 38 28	Tractor Arjun- Mahendra	13-Jan-26	3	MEWAKHA	Tyre blowout occurrence: unit out of stock				Pending	15-Dec-25

14-Jan-26	DAILY MAINTENANCE REPORT										
S/N	Asset Code	Description	Date of B/D	BD Days	Location	Breakdown Reason	Components	Technicians	Duration	Status	Maintained
HCV: 5											
1	321 39 142	Lowbed	14-Jan-26	2	WORKSHOP	Front support members were welded and reinforced	Electrodes	Bhm. Anil	1.5 hrs	Completed	16-Dec-25
2	321 39 103	Lowbed	14-Jan-26	2	WORKSHOP	Rear body (RR bed) support weldings carried out. kingpin wear issue to be attended resolving hard steering condition	Electrodes	Bhm., Anil. Sagar	1.5 hrs	Pending	11-Jan-26
3	GA2KHA9333	NOC	14-Jan-26	2	WORKSHOP	Clutch adjusted		Balmukunda	40 mm	Completed	28-Dec-25
4	321 39 137	Fighter-10 wheeler	14-Jan-26	2	WORKSHOP	Four worn tyres were removed and replaced with new units	Tyres	Alek	3 hrs	Completed	26-Dec-25
5	321 39 107	Fighter-10 wheeler	14-Jan-26	2	WORKSHOP	Hand brake system fault identified and corrected		Alek	15 mm	Completed	10-Jan-26
Excavator: 5											
6	321 45 42	CAT Excavator 323D3	11-Jan-26	5	0 KILO	Overhauled rock hammer assembly was reinstalled back on the machine. Salvaged bush and 3 new shims replaced	Salvaged bush. Shims	Kedar. Alek	2.5 hrs	Completed	8-Jan-26
7	321 45 40	CAT Excavator 323D3	13-Jan-26	3	WORKSHOP	Service tool compartment found damaged and removed by gas cutting.New light frame fabricated and reinstalled	Electrodes	Bhm. Anil. Alek	1.5 hrs	Completed	12-Jan-26
8	321 45 43	CAT Excavator 323D3	14-Jan-26	2	WORKSHOP	Hydraulic oil was drained. system flushed as required. and refilled	Hydraulic filter. Hydraulic Oil 220L	Ram. Kedar	2.5 hrs	Completed	10-Jan-26
9	321 45 39	Kobelco Excavator SK220	14 Jan-26	2	0 KILO	Rock breaker side plate bolt replaced	Salvaged side plate bolt	Kedar	25 mm	Completed	11 Jan-26
10	321 45 44	CAT Excavator 323D3	14-Jan-26	2	WORKSHOP	FR lamp replaced bucket repaired	Lamp assy. Electrodes	Ram. Sagar	1.5 hrs	Completed	5-Jan-26
Rock Hammer Breaker: 1											
11	321 17 04	Breaker hammer	13-Jan-26	3	WORKSHOP	Worn collar bush replaced. Chisel point reprofiled using gas cutting and installed back	Color bush	Kedar. Ram. Alek	2.5 hrs	Completed	-
Tractor: 1											
12	321 38 29	Tractor Arjun- Mahendra	14-Jan-26	2	WORKSHOP	Rear wheel hub bearing found defective; order placed		Balmukunda. Sagar	50 mm	Pending	12-Dec-25
Air Compressor: 1											
13	321 03 68	AIR COMPRESSOR(XAS 400-100)	14-Jan-26	2	WORKSHOP	Connector damage observed, machine returned from banande to workshop for rectification		Balmukunda, Sagar	2 hrs	Pending	7-Jan-26

16-Jan-26	DAILY MAINTENANCE REPORT										
S/N	Asset Code	Description	Date of B/D	BD Days	Location	Breakdown Reason	Components	Technicians	Duration	Status	Maintained
HCV: 4											
1	321 39 103	Lowbed	14-Jan-26	10	WORKSHOP	FR head lamp wiring ckts issue attended replacing with new sets; Kingpin wear issue attended using makeshift solution resolving hard steering condition; brake leathers changed, all new hinges were fabricated, welded and repaired; final checks n initial hours	FR head lamps, brake leathers.Electrodes	Balmukunda, Alek, Ram	9.5 hrs	Pending	11-Jan-26
2	321 39 133	Tata-10 wheeler	16-Jan-26	8	WORKSHOP	Welding repair carried out on front cabin mounting supports; damaged tyre removed and new tyre installed	Tyre, Electrodes	Anil, Alek	1.5 hrs	Completed	13-Jan-26
3	321 39 134	Eicher-10 wheeler	16-Jan-26	8	WORKSHOP	Brakes adjusted		Sagar	15 min	Completed	9-Jan-26
4	321 39 110	Fi ter-10 wheeler	16-Jan-26	8	WORKSHOP	Hydraulic tank (hami nut issue resolved		Sagar	45 min	Completed	10-Jan-26
Excavator: 3											
5	321 45 21	Komatsu Excavator PC-210	16-Jan-26	8	0 KILO	Breaker color bush pin: Thrust Wear Plates lock replaced	Colorbush pin, biscuit pin	Kedar	20 min	Completed	12-Jan-26
6	321 45 42	CAT Excavator 323D3	16-Jan-26	8	0 KILO	Rock breaker hammer bolts tightened		Kedar	30 min	Completed	11-Jan-26
7	321 45 43	CAT Excavator 323D3	16-Jan-26	8	CRUSHER	Bucket teeth lock pin changed	Pin	Kedar	15 min	Completed	14-Jan-26
Transit Mixture: 1											
8	320 39 108	T.M. CONMAT	16-Jan-26	8	WORKSHOP	Charging Hopper wiring issue attended		Ram	5 hrs	Completed	12-Jan-26
Backhoe: 2											
9	321 44 49	Backhoe-JCB	16-Jan-26	8	WORKSHOP	Lubricants applied to all pivot assemblies, linkages, and fittings	Grease	Binod	30 min	Completed	10-Jan-26
10	321 44 40	Backhoe-Bull	16-Jan-26	8	WORKSHOP	Periodic servicing carried out and greased	Engine Oil, Oil/fuel filters, Grease	Sagar, Ram, Binod	2 hrs	Completed	10-Jan-26
Light vehicle: 2											
11	GA4CHA1927	Mahindra Bolero	16-Jan-26	8	WORKSHOP	Strut assy changed	Struts	Sagar	45 min	Completed	-
12	341 03 40	Mahindra Bolero	16-Jan-26	8	WORKSHOP	RR u-bolts and centre bolts, leaf springs fabricated and repaired· suspension items inspected and greased	Centre bolt, U-bolts Electrodes, Grease	Kedar, Sagar	4.5 hrs	Completed	7-Jan-26

17-Jan-26	DAILY MAINTENANCE REPORT										
S/N	Asset Code	Description	Date of B/D	BD Days	Location	Breakdown Reason	Components	Technicians	Duration	Status	Maintained
HCV: 4											
1	321 39 138	Eicher-10 wheeler	11-Jan-26	13	WORKSHOP	Gear box overhauled	Pressure plate, release clutch bearing	Arjun, Alek, Balmukunda	9 hrs	Completed	8-Dec-25
2	321 39 103	Lowbed	14-Jan-26	10	WORKSHOP	Final torque tightening of all fasteners completed as per specification		Alek,. Ram	3 hrs	Completed	11-Jan-26
3	321 39 134	Eicher-10 wheeler	17-Jan-26	7	WORKSHOP	Clutch set issue		Arjun		Pending	16-Jan-26
4	321 39 139	Eicher-10 wheeler	5-Jan-26	19	WORKSHOP	Brakes adjusted		Sagar	20 min	Completed	25-Dec-25
Excavator: 6											
5	321 45 21	Komatsu Excavator PC-210	17-Jan-26	7	0 KILO	Breaker color bush lock replaced	Colorbush lock	Kedar	15 min	Completed	16-Jan-26
6	321 45 42	CAT Excavator 323D3	17-Jan-26	7	0 KILO	Rock breaker hammer thrust bolts replaced	Thrust bolts	Kedar, Sagar	4.5 hrs	Completed	16-Jan-26
7	321 45 29	XCMG Excavator 215C	17-Jan-26	7	BHAISIFORM	Starting issue resolved		Ram	15 min	Completed	21-Dec-25
8	321 45 43	CAT Excavator 323D3	17-Jan-26	7	TRT	Bucket teeths replaced and greased	Teeths, Grease	Ram, Binod	45 min	Completed	14-Jan-26
9	321 45 41	CAT Excavator 323D3	17-Jan-26	7	0 KILO	Bucket teeths replaced and greased	Teeths, Grease	Ram, Binod	30 min	Completed	11-Jan-26
10	321 45 16	Excavator 360 (Hyundai)	17-Jan-26	7	SISNE VIR	Pump assy issue; under maintenance		Balmukunda, Ram, Sagar	1.5 hrs	Pending	9-Jan-26
Air Compressor: 1											
11	321 03 68	AIR COMPRESSOR(XAS 400-100)	14-Jan-26	10	WORKSHOP	Connector pipeframe welded and repaired	Electrodes	Anil, Bhim	2 hrs	Completed	7-Jan-26
Wheel Loader: 2											
12	321 44 45	Wheel Loader-Lonking	17-Jan-26	7	WORKSHOP	Lubricated all joints	Grease	Binod	30 min	Completed	3-Jan-26
13	321 44 47	Wheel Loader-Lonking	17-Jan-26	7	WORKSHOP	Tyre puncture issue to be attended tomorrow		Sagar, Alek, Binod	30 min	Pending	24-Dec-25
Backhoe: 1											
14	321 44 40	Backhoe-Bull	17-Jan-26	7	WORKSHOP	Bucket teeths replaced and greased	Electrodes, Teeths and pins	Anil, Bhim, Alek	1 hr	Completed	16-Jan-26
Light vehicle: 1											
15	BAB3600	Scorpio-Combat	17-Jan-26	7	WORKSHOP	All discrepancies observed during routine checks were corrected and greased	Grease	Alek, Binod	30 min	Completed	24-Dec-25

18-Jan-26	DAILY MAINTENANCE REPORT										
S/N	Asset Code	Description	Date of B/D	BD Days	Location	Breakdown Reason	Components	Technicians	Duration	Status	Maintained
HCV: 2											
1	321 39 138	Eicher-10 wheeler	11-Jan-26	13	WORKSHOP	All final checks completed		Arjun	1.5 hrs	Completed	8-Dec-25
2	321 39 134	Eicher-10 wheeler	17-Jan-26	7	WORKSHOP	Gear box overhauled	Clutch assy set	Arjun, Alek	8.5 hrs	Completed	16-Jan-26
Excavator: 4											
3	321 45 42	CAT Excavator 323D3	17-Jan-26	7	0 KILO	Repaired bucket installed and greased	Bucket, Grease	Kedar, Sagar, Binod	30 mm	Completed	16-Jan-26
4	321 45 16	Excavator 360 (Hyundai)	17-Jan-26	7	WORKSHOP	Pump assy issue; under maintenance		Balmukunda, Ram, Sagar	9 hrs	Pending	9-Jan-26
5	321 45 43	CAT Excavator 323D3	18-Jan-26	6	CRUSHER	Lubricants applied to all pivot assemblies, linkages, and fittings	Grease	Binod	20 min	Completed	16-Jan-26
6	321 45 44	CAT Excavator 323D3	18-Jan-26	6	WORKSHOP	Bucket installed and greased	Bucket, Grease	Ram, Sagar	30 min	Completed	14-Jan-26
Rock Hammer Breaker: 1											
7	321 17 04	Breaker hammer	13-Jan-26	11	WORKSHOP	Rock breaker hammer housing bolts tightened		Kedar, Sagar, Binod	2 hrs	Completed	-
Fuel tank: 1											
8	321 20 30	Diesel Tanker	17-Jan-26	7	WORKSHOP	RR Fuel dispenser housing fabrication started	Electrodes	Anil, Bhim		Completed	16-Jan-26
Light vehicle: 3											
9	LUPR01001CHA3504	Mahindra Bolero	18-Jan-26	6	WORKSHOP	RR leaf spring bush changed and greased	Grease	Sagar, Binod	40 min	Completed	6-Jan-26
10	341 03 40	Mahindra Bolero	18-Jan-26	6	WORKSHOP	Brake linings replaced, brakes adjusted, strut assy changed	Brake linings, struts	Alek, Sagar, Arjun	4.5 hrs	Completed	16-Jan-26
11	GA4CHA1927	Mahindra Scorpio	18-Jan-26	6	WORKSHOP	Under panel cover bolts tightened		Sagar	20 mm	Completed	16-Jan-26

19-Jan-26	DAILY MAINTENANCE REPORT										
S/N	**Asset Code**	**Description**	**Date of B/D**	**BD Days**	**Location**	**Breakdown Reason**	**Components**	**Technicians**	**Duration**	**Status**	**Maintained**
HCV: 3											
1	321 39 134	Eicher-10 wheeler	17-Jan-26	7	WORKSHOP	Gear box overhauled, final checks completed		Arjun, Alek	30 min	Completed	16-Jan-26
2	321 39 110	Eicher-10 wheeler	19-Jan-26	5	WORKSHOP	Cracked nylon pipes issue resolved; clutch pipe breakage leading to loss of clutch actuation resolved	Repaired air socket; clutch pipe	Balmukunda, Arjun	2 hrs	Completed	16-Jan-26
3	321 39 107	Eicher-10 wheeler	19-Jan-26	5	WORKSHOP	Boom cylinder seal kit issue;order placed		Arjun		Pending	14-Jan-26
Excavator: 3											
4	321 45 16	Excavator 360 (Hyundai)	17-Jan-26	7	WORKSHOP	Pump assy and injector nozzle issue; to be sent for repair		Alek, Ram, Binod	2.5 hrs	Pending	9-Jan-26
5	321 45 29	XCMG Excavator 215C	19-Jan-26	5	DHOVAN	Pump assy leakage issue;Oil pressure switch replaced; O rings replaced; hydraulic and engine oil replenished	Salvaged oil pressure switch;, o-ring,Hydraulic and engine oil	Balmukunda, Arjun	4.5 hrs	Completed	17-Jan-26
6	321 45 13	CAT EXCAVATOR	19-Jan-26	5	CRUSHER	Preliminary dismantling carried out prior to shifting to the workshop		Kedar, Sagar, Binod	6.5 hrs	Pending	-
Backhoe: 1											
7	321 44 40	Backhoe-Bull	19-Jan-26	5	WORKSHOP	Tyre burst detected and a new tyre was installed	Tyre	Sagar, Kedar, Arjun	1.5 hrs	Completed	17-Jan-26
Light vehicle: 3											
8	321 44 30	Mahindra Bolero	10-Jan-26	14	WORKSHOP	Fuel pump issue; repaired unit replaced	Repaired fuel pump	Balmukunda, Alek	4.5 hrs	Completed	6-Jan-26
9	LU3031023CHA6160	Toyota hilux	19-Jan-26	5	WORKSHOP	Tyre puncture issue resolved		Sagar, Binod	45 min	Completed	-
10	341 03 40	Mahindra Bolero	19-Jan-26	5	WORKSHOP	RR u-bolt replaced	U bolt	Arjun,Sagar	35 min	Completed	18-Jan-26
Air Compressor: 1											
11	321 03 68	AIR COMPRESSOR(XAS 400-100)	19-Jan-26	5	WORKSHOP	Subjected to abnormal load issue resolved		Kedar	45 min	Completed	14-Jan-26
Boomer: 1											
12	321 39 126	Epiroc	19-Jan-26	5	WORKSHOP	Engine starting issue diagnosed and resolved		Ram	45 min	Completed	-

20-Jan-26		DAILY MAINTENANCE REPORT									
S/N	**Asset Code**	**Description**	**Date of B/D**	**BD Days**	**Location**	**Breakdown Reason**	**Components**	**Technicians**	**Duration**	**Status**	**Maintained**
HCV: 2											
1	321 39 124	Eicher-10 wheeler	20-Jan-26	4	WORKSHOP	Starting issue resolved		Arjun	15 min	Completed	11-Jan-26
2	321 39 133	Tata-10 wheeler	20-Jan-26	4	WORKSHOP	Brakes adjusted		Arjun	15 min	Completed	16-Jan-26
Excavator: 2											
3	321 45 19	Komatsu Excavator PC-210	20-Jan-26	4	WORKSHOP	Bucket teeth lock, bush locks and shims replaced and parts-welded	Shims, locks and pins, Electrodes	Kedar, Bhim	1.5 hr	Completed	12-Jan-26
4	321 45 13	CAT EXCAVATOR	19-Jan-26	5	CRUSHER	Preliminary dismantling carried out prior to shifting completed		Kedar, Sagar, Binod	6 hrs	Completed	-
Light vehicle: 1											
5	321 44 30	Mahindra Bolero	10-Jan-26	14	WORKSHOP	Final checks completed and full servicing	Engine oil, oil filter, air filter, diesel filter	Balmukunda, Alok	3.5 hrs	Completed	6-Jan-26

21-Jan-26		DAILY MAINTENANCE REPORT									
S/N	**Asset Code**	**Description**	**Date of B/D**	**BD Days**	**Location**	**Breakdown Reason**	**Components**	**Technicians**	**Duration**	**Status**	**Maintained**
HCV: 3											
1	321 39 124	Eicher-10 wheeler	21-Jan-26	3	ARMY CAMP AREA	Following a rollover incident, the vehicle was shifted to the workshop for further assessment		Arjun, Kedar, Bahnukunda, Sagar	2.5 hrs	Completed	20-Jan-26
2	321 39 107	Eicher-10 wheeler	19-Jan-26	5	WORKSHOP	Boom cylinder replaced	Salvaged Boom cylinder	Arjun, Ram, Alek, Manish	5.5 hrs	Completed	14-Jan-26
3	321 39 97	Eicher-10 wheeler	21-Jan-26	3	WORKSHOP	Cabin struts and bolts changed	Cabit strut assy, cabin bolts	Arjun, Manish	1.5 hrs	Completed	13-Jan-26
Excavator: 1											
4	321 45 38	Komatsu Excavator PC-210	21-Jan-26	3	THAUWA	Air and a/c filter changed	Air filter, AC filter	Kedar	15 min	Completed	9-Jan-26
Light vehicle: 1											
5	321 44 30	Mahindra Bolero	21-Jan-26	3	WORKSHOP	FR leaf springs damaged: order placed **P.R. No: 688 ; SN: 64**		Alek, Sagar, Manish	1 hr	Pending	20-Jan-26
Roller: 1											
6	321 46 04	Dynapac Roller	21-Jan-26	3	MAT	Control valve replaced		Bahnukunda, Ram	1 hr	Completed	10-Jan-26

22-Jan-26		DAILY MAINTENANCE REPORT									
S/N	Asset Code	Description	Date of B/D	BD Days	Location	Breakdown Reason	Components	Technicians	Duration	Status	Maintained
		HCV: 3									
1	321 39 134	Eicher-10 wheeler	22-Jan-26	2	WORKSHOP	RR Buggy lock fabricated and installed	Electrodes	Anil. Bhim	1.5 hrs	Completed	17-Jan-26
2	321 39 97	Eicher-10 wheeler	22-Jan-26	2	WORKSHOP	Tyre pressure check		Sagar	15 min	Completed	21-Jan-26
3	321 39 110	Eicher-10 wheeler	22-Jan-26	2	WORKSHOP	Head lamp bulb replaced. air pipe lines issue resolved and greased	Bulb. Grease	Bahmukunda. Alek. Binod	30 min	Completed	19-Jan-26
		Excavator: 3									
4	321 45 39	Kobelco Excavator SK220	22-Jan-26	2	WORKSHOP	Lubricants applied to all pivot assemblies, linkages, and fittings	Grease	Binod	45 min	Completed	14-Jan-26
5	321 45 41	CAT Excavator 323D3	22-Jan-26	2	WORKSHOP	Bucket boom cylinder replaced	Repaired boom cylinder	Kedar. Sagar. Arjun, Manish	4.5 hrs	Completed	17-Jan-26
6	321 45 29	XCMG Excavator 215C	22-Jan-26	2	DHOVAN	Periodic maintenance completed	Hydraulic Oil. Engine Oil	Kedar, Arjun. Manish	3.5 hrs	Completed	19-Jan-26
		Light vehicle: 2									
7	321 44 30	Mahindra Bolero	21-Jan-26	3	WORKSHOP	Final checks completed		Arjun. Sagar	15 min	Completed	20-Jan-26
8	LUPR01001CHA3504	Mahindra Bolero	22-Jan-26	2	WORKSHOP	RR leaf springs changed	RR Leaf srpings	Sagar. Alek. Binod	2.5 hrs	Completed	18-Jan-26
		Backhoe: 1									
9	321 44 49	Backhoe-JCB	22-Jan-26	2	WORKSHOP	Bucket teeths replaced and greased	Bucket teeths. Grease	Bhim. Manish. Binod	1 hr	Completed	16-Jan-26
		Tractor: 1									
10	321 38 29	Tractor Arjun- Mahendra	22-Jan-26	2	WORKSHOP	Starting issue resolved		Ram	20 min	Completed	20-Jan-26
		Wheel Loader: 1									
11	321 44 47	Wheel Loader-Lonking	22-Jan-26	2	WORKSHOP	Bucket teeths and adaptor replaced	Bucket Teeths and adaptors	Bhim. Anil	3.5 hrs	Completed	17-Jan-26
		Grader: 1									
12		HIDROMEK MG 430	22-Jan-26	2	WORKSHOP	Lift cylinder.Tilt cylinder. Steering cylinder seal kits replaced	Seal kits	Alek. Sagar. Bahmukunda. Ram	4.5 hrs	Completed	4-Jan-26

23-Jan-26	DAILY MAINTENANCE REPORT										
S/N	Asset Code	Description	Date of B/D	BD Days	Location	Breakdown Reason	Components	Technicians	Duration	Status	Maintained
HCV: 4											
1	321 39 114	Eicher-10 wheeler	4-Jan-26	20	WORKSHOP	Silencer flexible pipe replaced; hydraulic bkts replaced	Silencer pipe, bracketes	Arjun, Manish	1.5 hrs	Pending	-
2	321 39 103	Lowbed	23-Jan-26	1	WORKSHOP	Brakes adjusted and greased	Grease	Arjun, Binod	25 min	Completed	14-Jan-26
3	321 39 141	TATA Lowbed	23-Jan-26	1	WORKSHOP	Welding repairs carried out on all affected parts; rear bed hooks fabricated and securely installed	Electrodes	Anil, Raymond	4 hrs	Completed	-
4	PR101001CHA4552	Truck	23-Jan-26	1	WORKSHOP	Tyre pressure checked; Tyre sealant used	Sealeant	Sagar	20 mnn	Completed	-
Excavator: 7											
5	321 45 41	CAT Excavator 323D3	23-Jan-26	1	0 KILO	Bucket teeth and lock pin replaced then greased	Bucket teeth and lock pin, Grease	Kedar, Sagar, Binod	20 mnn	Completed	22-Jan-26
6	321 45 40	CAT Excavator 323D3	23-Jan-26	1	WORKSHOP	Repaired bucket replaced and greased	Repaired bucket, Grease	Kedar, Manish	45 min	Completed	13-Jan-26
7	321 45 39	Kobelco Excavator SK220	23-Jan-26	1	0 KILO	Lubricants applied to all pivot assemblies, linkages, and fittings of rock hammer breaker	Grease	Sagar, Binod	10 min	Completed	22-Jan-26
8	321 45 29	XCMG Excavator 215C	23-Jan-26	1	DHOVAN	Starting issue resolved, old battery replaced	Salvaged battery	Kedar, Ram	3 hrs	Completed	22-Jan-26
9	321 45 21	Komatsu Excavator PC-210	23-Jan-26	1	0 KILO	Comprehensive lubrication of all moving components completed	Grease	Sagar, Binod	15 mnn	Completed	17-Jan-26
10	321 45 43	CAT Excavator 323D3	23-Jan-26	1	CRUSHER	Lubricants applied to all pivot assemblies, linkages, and fittings	Grease	Sagar, Binod	20 min	Completed	18-Jan-26
11	321 45 44	CAT Excavator 323D3	23-Jan-26	1	0 KILO	Lubricated all joints	Bucket, Grease	Sagar, Binod	15 min	Completed	18-Jan-26
Light vehicle: 2											
12	GA4CHA1930	MAHINDRA BOLERO	23-Jan-26	1	WORKSHOP	FR & RR U-j cross changed	Uj cross	Alek, Manish	1.5 hrs	Completed	6-Jan-26
13	341 03 40	Mahindra Bolero	23-Jan-26	1	WORKSHOP	Tyre repaired	Tube, Salvaged Tyre	Arjun,Sagar	35 min	Completed	19-Jan-26
Backhoe: 1											
14	321 44 40	Backhoe-Bull	23-Jan-26	1	WORKSHOP	Diesel filter bracket issue resolved; Lubricants applied to all pivot assemblies, linkages, and fittings	Grease, Electrodes	Arjun, Binod	1.5 hrs	Completed	19-Jan-26
Wheel Loader: 1											
15	321 44 47	Wheel Loader-Lonking	22-Jan-26	2	WORKSHOP	Bucket teeths and adaptor replaced	Electrodes	Bhim, Anil	3.5 hrs	Completed	17-Jan-26
Transit Mixture: 1											
16	321 39 152	TATA putzmeister Mixture	23-Jan-26	1	WORKSHOP	Pick up issue attended and greased	Grease	Binod, Balmukunda	40 min	Completed	7-Jan-26
Mobile Crane: 1											
17	321 43 18	Truck Mount Crane(Zoomlin) 5tons	23-Jan-26	1	WORKSHOP	Cabin RR window repaired		Sagar, Binod	45 mnn	Completed	-

23-Jan-26	DAILY MAINTENANCE REPORT										
S/N	Asset Code	Description	Date of B/D	BD Days	Location	Breakdown Reason	Components	Technicians	Duration	Status	Maintained
HCV: 4											
1	321 39 114	Eicher-10 wheeler	4-Jan-26	20	WORKSHOP	Silencer flexible pipe replaced; hydraulic bkts replaced	Silencer pipe, bracketes	Arjun, Manish	1.5 hrs	Pending	-
2	321 39 103	Lowbed	23-Jan-26	1	WORKSHOP	Brakes adjusted and greased	Grease	Arjun, Binod	25 min	Completed	14-Jan-26
3	321 39 141	TATA Lowbed	23-Jan-26	1	WORKSHOP	Welding repairs carried out on all affected parts; rear bed hooks fabricated and securely installed	Electrodes	Anil, Raymond	4 hrs	Completed	-
4	PR101001CHA4552	Truck	23-Jan-26	1	WORKSHOP	Tyre pressure checked; Tyre sealant used	Sealeant	Sagar	20 mnn	Completed	-
Excavator: 7											
5	321 45 41	CAT Excavator 323D3	23-Jan-26	1	0 KILO	Bucket teeth and lock pin replaced then greased	Bucket teeth and lock pin, Grease	Kedar, Sagar, Binod	20 mnn	Completed	22-Jan-26
6	321 45 40	CAT Excavator 323D3	23-Jan-26	1	WORKSHOP	Repaired bucket replaced and greased	Repaired bucket, Grease	Kedar, Manish	45 min	Completed	13-Jan-26
7	321 45 39	Kobelco Excavator SK220	23-Jan-26	1	0 KILO	Lubricants applied to all pivot assemblies, linkages, and fittings of rock hammer breaker	Grease	Sagar, Binod	10 min	Completed	22-Jan-26
8	321 45 29	XCMG Excavator 215C	23-Jan-26	1	DHOVAN	Starting issue resolved, old battery replaced	Salvaged battery	Kedar, Ram	3 hrs	Completed	22-Jan-26
9	321 45 21	Komatsu Excavator PC-210	23-Jan-26	1	0 KILO	Comprehensive lubrication of all moving components completed	Grease	Sagar, Binod	15 mnn	Completed	17-Jan-26
10	321 45 43	CAT Excavator 323D3	23-Jan-26	1	CRUSHER	Lubricants applied to all pivot assemblies, linkages, and fittings	Grease	Sagar, Binod	20 min	Completed	18-Jan-26
11	321 45 44	CAT Excavator 323D3	23-Jan-26	1	0 KILO	Lubricated all joints	Bucket, Grease	Sagar, Binod	15 min	Completed	18-Jan-26
Light vehicle: 2											
12	GA4CHA1930	MAHINDRA BOLERO	23-Jan-26	1	WORKSHOP	FR & RR U-j cross changed	Uj cross	Alek, Manish	1.5 hrs	Completed	6-Jan-26
13	341 03 40	Mahindra Bolero	23-Jan-26	1	WORKSHOP	Tyre repaired	Tube, Salvaged Tyre	Arjun,Sagar	35 min	Completed	19-Jan-26
Backhoe: 1											
14	321 44 40	Backhoe-Bull	23-Jan-26	1	WORKSHOP	Diesel filter bracket issue resolved; Lubricants applied to all pivot assemblies, linkages, and fittings	Grease, Electrodes	Arjun, Binod	1.5 hrs	Completed	19-Jan-26
Wheel Loader: 1											
15	321 44 47	Wheel Loader-Lonking	22-Jan-26	2	WORKSHOP	Bucket teeths and adaptor replaced	Electrodes	Bhim, Anil	3.5 hrs	Completed	17-Jan-26
Transit Mixture: 1											
16	321 39 152	TATA putzmeister Mixture	23-Jan-26	1	WORKSHOP	Pick up issue attended and greased	Grease	Binod, Balmukunda	40 min	Completed	7-Jan-26
Mobile Crane: 1											
17	321 43 18	Truck Mount Crane(Zoomlin) 5tons	23-Jan-26	1	WORKSHOP	Cabin RR window repaired		Sagar, Binod	45 mnn	Completed	-

24-Jan-26	DAILY MAINTENANCE REPORT										
S/N	**Asset Code**	**Description**	**Date of B/D**	**BD Days**	**Location**	**Breakdown Reason**	**Components**	**Technicians**	**Duration**	**Status**	**Maintained**
HCV: 5											
1	321 39 114	Eicher-10 wheeler	4-Jan-26	23	WORKSHOP	Replaced self-assembly, dynamo, fuel pump, air compressor, and associated air piping	Repaired fuel pump.starter motor.dyanmo.air compressor, pipe and fittings	Arjun, Ram, Balmukunda, Kedar, Alek	9 hrs	Pending	-
2	321 39 97	Eicher-10 wheeler	24-Jan-26	3	WORKSHOP	Stone lodged between the twin tyres was removed; tyre pressure was checked and inflated to the required level.		Manish	20 min	Completed	22-Jan-26
3	321 39 110	Eicher-10 wheeler	24-Jan-26	3	WORKSHOP	Air filter cleaned and greased		Binod	20 min	Completed	22-Jan-26
4	LUPRO1O4057	Tata truck	24-Jan-26	3	WORKSHOP	Uj cross replaced, Silencer parts welded and repaired then greased	Uj cross, electrodes, grease	Alek, Bhim	3.5 hrs	Completed	-
5	321 39 157	Tata-10 wheeler	24-Jan-26	3	WORKSHOP	Rear buggy lock fabricated and installed	Electrodes	Bhim, Anil	1.5 hrs	Completed	16-Dec-25
Wheel Loader: 1											
5	321 44 45	Wheel Loader-Lonking	24-Jan-26	3	WORKSHOP	Lubricated all joints	Grease	Binod	30 min	Completed	17-Jan-26
Air Compressor: 1											
6	321 03 68	AIR COMPRESSOR(XAS 400-100)	24-Jan-26	3	WORKSHOP	Rear leaf spring hanger bracket found broken; new hanger fabricated and fitted		Balmukunda, Sagar	2.5 hrs	Completed	19-Jan-26
Light vehicle: 2											
7	321 44 38	Mahindra Bolero	24-Jan-26	3	WORKSHOP	Punctured tyre repaired using makeshift solution	Omni patch	Sagar	1 hr	Completed	4-Jan-26
8	321 44 30	Mahindra Bolero	24-Jan-26	3	WORKSHOP	FR LH Leaf springs and centre bolt replaced	Leaf springs and centre bolt	Sagar, Manish	3 hrs	Completed	21-Jan-26
Shotcrete Machine: 1											
9	321 19 107	Shotcrete Machine	24-Jan-26	3	WORKSHOP	Hydraulic oil replenished and system commissioning successfully completed	Hydraulic Oil	Yash, Manish	1 hrs	Completed	-

25-Jan-26	DAILY MAINTENANCE REPORT										
S/N	Asset Code	Description	Date of B/D	BD Days	Location	Breakdown Reason	Components	Technicians	Duration	Status	Maintained
HCV: 7											
1	321 39 114	Eicher-10 wheeler	4-Jan-26	23	WORKSHOP	Ribbed V-belt renewal completed. Diaphragm set (Qty. 4) attended: 2 replaced with new, 1 repaired, and 1 replaced with a salvaged repaired unit. Two air pressure sockets were replaced, along with radiator brackets and radiator assembly fitment	V belt, diaphragms. air pressure pipe	Arjun, Ram, Balmukunda, Kedar, Manish	7.5 hrs	Pending	-
2	321 39 139	Eicher-10 wheeler	25-Jan-26	2	WORKSHOP	Tyre puncture rectified		Sagar	1 hr	Completed	5-Jan-26
3	321 39 133	Tata-10 wheeler	25-Jan-26	2	WORKSHOP	Engine Oil replenished by 4L	Engine Oil	Sagar	35 min	Completed	20-Jan-26
4	321 39 157	Tata-10 wheeler	25-Jan-26	2	WORKSHOP	Cabin room bulb ckts issue attended		Ram, Alek	1 hr	Completed	16-Dec-25
5	321 39 134	Eicher-10 wheeler	25-Jan-26	2	WORKSHOP	Re-fabrication and fitment of diaphragm brackets completed, along with installation of multiple air pressure hoses/pipes	Electrodes. 2 Air pressure pipe	Arjun, Manish, Bhim	2 hrs	Completed	22-Jan-26
6	321 39 142	Lowbed	25-Jan-26	2	WORKSHOP	Punctured tyre attended and repaired. Rear bed structural parts were welded and strengthened.	Electrodes	Anil, Sagar, Manish	1.5 hrs	Completed	24-Jan-26
7	321 39 93	Eicher-6 wheeler	25-Jan-26	2	WORKSHOP	Front leaf springs defective; under maintenance		Alek, Balmukunda	1 hr	Pending	5-Jan-26
Light vehicle: 2											
8	341 03 43	MAHINDRA BOLERO	25-Jan-26	2	WORKSHOP	Flange yoke and teeth replaced and greased	Yoke and teeth. Grease	Alek, Sagar, Manish, Binod	3 hrs	Completed	19-Dec-25
9	321 44 30	Mahindra Bolero	25-Jan-26	2	WORKSHOP	4 Wheel Uj cross, Flange, brake pads changed and gear oil replenished by 5L and greased	Uj cross, Flange, Gear oil. Brake pad	Manish, Alek, Binod	4 5 hrs	Completed	24-Jan-26
Tractor: 1											
10	321 38 29	Tractor Arjun- Mahendra	25-Jan-26	2	WORKSHOP	Starting issue resolved		Ram, Alek	1 hr	Completed	22-Jan-26
Backhoe: 1											
11	321 44 40	Backhoe-Bull	25-Jan-26	2	WORKSHOP	Bucket teeth were welded and repaired as required	Electrodes	Bhim, Anil	45 min	Completed	23-Jan-26
Shotcrete Machine: 1											
12	321 19 107	Shotcrete Machine	25-Jan-26	2	TRT	Motor issue attended and resolved		Chandra	4 hrs	Completed	24-Jan-26
Roller: 1											
13	321 46 04	Dynapac Roller	25-Jan-26	2	MAT	Lubricated all joints		Kedar, Binod	15 min	Completed	21-Jan-26
Excavator: 3											
14	321 45 19	Komatsu Excavator PC-210	25-Jan-26	2	RIVER BED	Bucket teeths and lock pins replaced	Teeths and lock pins	Manish	20 min	Completed	20-Jan-26
15	321 45 38	Komatsu Excavator PC-210	25-Jan-26	2	ADIT	Lubricants applied to all pivot assemblies, linkages, and fittings	Grease	Kedar, Binod	15 min	Completed	21-Jan-26
16	321 45 42	CAT Excavator 323D3	25-Jan-26	2	THAUWA	Comprehensive lubrication of all moving components completed	Grease	Kedar, Binod	15 min	Completed	17-Jan-26

26-Jan-26	DAILY MAINTENANCE REPORT										
S/N	Asset Code	Description	Date of B/D	BD Days	Location	Breakdown Reason	Components	Technicians	Duration	Status	Maintained
HCV: 3											
1	321 39 114	Eicher-10 wheeler	4-Jan-26	23	WORKSHOP	Intercooler fitted; Radiator assy bkts fabricated and installed	Intercooler, Bkts	Arjun, Ram, Binod	2.5 hrs	Pending	-
2	321 39 93	Eicher-6 wheeler	25-Jan-26	2	WORKSHOP	Front leaf springs defective; Maintenance completed		Alek, Balmukunda, Kedar	3 hrs	Completed	5-Jan-26
3	321 39 142	Lowbed	26-Jan-26	1	WORKSHOP	New tyre replaced	Tyre	Sagar, Binod	55 min	Completed	25-Jan-26
Light vehicle: 1											
4	321 44 30	Mahindra Bolero	25-Jan-26	2	WORKSHOP	Tail pinion seal, brakes adjusted, Brake pipe under repiar and gear oil replenished	Tail pinion seal, Gear Oil	Arjun, Sagar, Alek	4.5 hrs	Pending	24-Jan-26
Tractor: 1											
5	PR1001001TA8885	John Deere- Mahendra	26-Jan-26	1	WORKSHOP	Connector welded; RR wheel bearing issue	Electrodes	Anil, Bhim	40 min	Completed	-
Boomer: 1											
6	321 39 127	Epiroc	26-Jan-26	1	TRT	Comprehensive preventive maintenance carried out		Indrajit, Manish	7 hrs	Pending	-
Transit Mixture: 2											
7	321 39 151	TATA Putzmeister Mixture	26-Jan-26	1	WORKSHOP	Required areas lubricated	Grease	Binod	20 min	Completed	6-Dec-25
8	321 39 152	TATA putzmeister Mixture	26-Jan-26	1	WORKSHOP	Punctured Tyre replaced with new unit	New tyre	Sagar	45 min	Completed	23-Jan-26
Excavator: 2											
9	321 45 40	CAT Excavator 323D3	26-Jan-26	1	TRT	Lubricants applied to all pivot assemblies, linkages, and fittings	Grease	Sagar, Binod	15 min	Completed	23-Jan-26
10	321 45 41	CAT Excavator 323D3	26-Jan-26	1	0 KILO	Repaired bucket replaced and greased	Repaired Bucket, Grease	Sagar, Binod	30 min	Completed	23-Jan-26

27-Jan-26	DAILY MAINTENANCE REPORT										
S/N	**Asset Code**	**Description**	**Date of B/D**	**BD Days**	**Location**	**Breakdown Reason**	**Components**	**Technicians**	**Duration**	**Status**	**Maintained**
HCV: 3											
1	321 39 114	Eicher-10 wheeler	4-Jan-26	26	WORKSHOP	Air cleaner element replaced. Fuel pump & nozzles inspected	Air cleaner	Arjun, Ram, Balmukunda	5 hrs	Pending	-
2	321 39 111	Eicher-6 wheeler	27-Jan-26	3	WORKSHOP	Lubrication applied to all pivot joints, linkages, and fittings	Grease	Binod	15 min	Completed	2-Jan-26
3	321 39 133	Tata-10 wheeler	25-Jan-26	5	WORKSHOP	Greasing performed on all serviceable points	Grease	Binod	15 min	Completed	20-Jan-26
Light vehicle: 1											
4	321 44 30	Mahindra Bolero	25-Jan-26	5	WORKSHOP	Tail pinion seal, brakes adjusted, Brake pipe under repiar and gear oil replenished	Repaired brake pipe, Gear Oil	Arjun, Balmukunda	2 hrs	Completed	24-Jan-26
Boomer: 1											
5	321 39 127	Epiroc	26-Jan-26	4	TRT	Comprehensive preventive maintenance carried out	Transmission oil filter, Engine oil	Indrajit, Manish	7 hrs	Completed	-
Transit Mixture: 1											
6	321 39 151	TATA Putzmeister Mixture	27-Jan-26	3	WORKSHOP	Brakes adjusted		Arjun	20 min	Completed	26-Jan-26
Excavator: 2											
7	321 45 40	CAT Excavator 323D3	27-Jan-26	3	TRT	All Bucket teeths replaced	Bucket teeths, locks & pins	Kedar	20 min	Completed	26-Jan-26
8	321 45 19	Komatsu Excavator PC-210	27-Jan-26	3	RIVER BED	Damaged bucket replaced with repaired unit and greased	Bucket, Locks and fabricated pins	Kedar, Sagar, Binod	1.5 hr	Completed	25-Jan-26

28-Jan-26	DAILY MAINTENANCE REPORT										
S/N	**Asset Code**	**Description**	**Date of B/D**	**BD Days**	**Location**	**Breakdown Reason**	**Components**	**Technicians**	**Duration**	**Status**	**Maintained**
HCV: 6											
1	321 39 114	Eicher-10 wheeler	4-Jan-26	26	WORKSHOP	Fuel pump and injector nozzles to send for repair		Ram, Balmukunda, Arjun	5 hrs	Pending	-
2	321 39 125	Mini Truck SML (4 Wheeler	11-Jan-26	19	WORKSHOP	Placed order received; Gear box under maintenance		Arjun, Balmukunda	1.5 hrs	Pending	9-Jan-26
3	321 39 97	Eicher-10 wheeler	28-Jan-26	2	WORKSHOP	Engine oil replenished by 4L	Engine Oil	Arjun	15 min	Completed	24-Jan-26
4	321 39 110	Eicher-10 wheeler	28-Jan-26	2	WORKSHOP	Rear bogie side frames repaired		Anil, Bhim	30 min	Completed	24-Jan-26
5	321 39 107	Eicher-10 wheeler	28-Jan-26	2	WORKSHOP	Air pressure pipe issue resolved using makeship solution, Auto slack adjusters rear replaced	Auto slack adjusters	Arjun, Manish, Balmukunda	2.5 hrs	Completed	19-Jan-26
6	321 39 134	Eicher-10 wheeler	28-Jan-26	2	WORKSHOP	Brakes adjusted		Arjun	15 min	Completed	25-Jan-26
Backhoe: 1											
7	321 44 49	Backhoe-JCB	28-Jan-26	2	WORKSHOP	Lubricants applied to all pivot assemblies, linkages, and fittings	Grease	Binod	20 min	Completed	22-Jan-26
Excavator: 3											
8	321 45 39	Kobelco Excavator SK220	28-Jan-26	2	WORKSHOP	Breaker pipe inspected; Lubricants applied to all pivot assemblies, linkages, and fittings of rock hammer breaker	Grease	Kedar, Binod	30 min	Completed	23-Jan-26
9	321 45 43	CAT Excavator 323D3	28-Jan-26	2	MAT	Lubricants applied to all pivot assemblies, linkages, and fittings	Grease	Kedar, Binod	30 min	Completed	23-Jan-26
10	321 45 29	XCMG Excavator 215C	28-Jan-26	2	BHAISEFORM	Lubricated all joints	Grease	Sagar, Binod	45 min	Completed	23-Jan-26
Tractor: 1											
11	321 38 29	Tractor Arjun- Mahendra	28-Jan-26	2	WORKSHOP	Rear water sprayer welded and repaired and greased	Electrodes, Grease	Anil, Binod	30 min	Completed	25-Jan-26
Rock Crusher: 1											
12	321 10 14	CHIEFTAIN 1700AL	28-Jan-26	2	CRUSHER	Battery replaced from 321 39 132	Battery	Ram, Sagar	20 min	Completed	-
Wheel Loader: 1											
13	321 44 45	Wheel Loader-Lonking	28-Jan-26	2	WORKSHOP	Lubricated all joints	Grease	Sagar, Binod	30 min	Completed	24-Jan-26
Light vehicle: 1											
14	341 03 43	MAHINDRA BOLERO	28-Jan-26	2	WORKSHOP	Shackle plates replaced, Rear leaf springs changed and greased	Leaf springs, Centre bolt, Shackle plate, Grease	Arjun, Manish, Sagar, Binod	3 hrs	Completed	25-Jan-26

29-Jan-26	DAILY MAINTENANCE REPORT										
S/N	**Asset Code**	**Description**	**Date of B/D**	**BD Days**	**Location**	**Breakdown Reason**	**Components**	**Technicians**	**Duration**	**Status**	**Maintained**
HCV: 3											
1	321 39 125	Mini Truck SML (4 Wheeler)	11-Jan-26	19	WORKSHOP	Gear box overhauled	Counter gear shaft;spindle,needle roller bearing,thrust washer, Gear Oil	Arjun, Manish, Balmukunda	8 hrs	Completed	9-Jan-26
2	321 39 133	Tata-10 wheeler	29-Jan-26	1	WORKSHOP	Brakes adjusted; Greasing performed on all serviceable points.	Grease	Arjun, Binod	25 min	Completed	25-Jan-26
3	321 39 93	Eicher-6 wheeler	29-Jan-26	1	WORKSHOP	2 new FR LH leaf springs to be added; under maintenance		Arjun, Manish, Balmukunda	1.5 hrs	Pending	25-Jan-26
Backhoe: 1											
4	321 44 40	Backhoe-Bull	29-Jan-26	1	WORKSHOP	Lubricants applied to all pivot assemblies, linkages, and fittings	Grease	Binod, Kedar	30 min	Completed	25-Jan-26
Excavator: 3											
5	321 45 38	Komatsu Excavator PC-210	29-Jan-26	1	ADIT	Track chain dislogged issue resolved and greased	Grease	Kedar, Binod	1.5 hrs	Completed	25-Jan-26
6	321 45 41	CAT Excavator 323D3	29-Jan-26	1	0 KILO	Bucket teeth, lock and pin replaced; Counter weight under panel bolts issue; under maintenance	Bucket teeth, lock and pins	Kedar, Binod	1 hr	Pending	26-Jan-26
7	321 45 21	Komatsu Excavator PC-210	29-Jan-26	1	ADIT	Rock breaker bush to replace; shifted to workshop		Kedar, Binod	1.5 hrs	Pending	23-Jan-26
Shotcrete Machine: 1											
8	-	Shotcrete Machine	29-Jan-26	1	WORKSHOP	Shotcrete accelerator hose replaced	Dosing pump hose	Kedar	1 hr	Completed	23-Jan-26

30-Jan-26	DAILY MAINTENANCE REPORT										
S/N	**Asset Code**	**Description**	**Date of B/D**	**BD Days**	**Location**	**Breakdown Reason**	**Components**	**Technicians**	**Duration**	**Status**	**Maintained**
HCV: 3											
3	321 39 93	Eicher-6 wheeler	29-Jan-26	1	WORKSHOP	FR RH LH 2 leaf springs each added; Head lamp electrical ckts issue resolved		Arjun, Manish, Bahnukunda, Ram	3.5 hrs	Completed	25-Jan-26
2	321 39 139	Eicher-10 wheeler	30-Jan-26	0	WORKSHOP	FR Tyre puncture rectified		Arjun, Manish	1.5 hrs	Completed	25-Jan-26
3	321 39 107	Eicher-10 wheeler	30-Jan-26	0	WORKSHOP	Intercooler housing found defective; resolved		Arjun	2.5 hrs	Completed	28-Jan-26
4	321 39 97	Eicher-10 wheeler	30-Jan-26	0	WORKSHOP	Air filter element cleaned		Ram	10 min	Completed	28-Jan-26
5	321 39 111	Eicher-6 wheeler	30-Jan-26	0	WORKSHOP	Accelerator wire spring found defective; replaced; and brakes adjusted	Salvaged srping	Arjun	25 min	Completed	27-Jan-26
Light vehicle: 1											
6	341 03 43	MAHINDRA BOLERO	30-Jan-26	0	WORKSHOP	RR RH LH brake leathers changed	Brake leathers	Arjun, Manish	1.5 hrs	Completed	28-Jan-26
Excavator: 3											
7	321 45 41	CAT Excavator 323D3	29-Jan-26	1	0 KILO	Counter weight under panel bolts issue; bolts replaced	Counter weight bolts	Kedar, Sagar	1.5 hrs	Completed	26-Jan-26
8	321 45 21	Komatsu Excavator PC-210	29-Jan-26	1	ADIT	Repaired Rock hammer breaker replaced; nitrogen repelenished; Full servicing	Repaired breaker; Air filter,engine oil filter, fuel filters, engine oil	Kedar, Sagar	3.5 hrs	Completed	23-Jan-26
9	321 45 19	Komatsu Excavator PC-210	29-Jan-26	1	RIVER BED	Track chain bolts tightened and greased	Grease	Arjun, Manish	1 hr	Completed	27-Jan-26

31-Jan-26	DAILY MAINTENANCE REPORT										
S/N	**Asset Code**	**Description**	**Date of B/D**	**BD Days**	**Location**	**Breakdown Reason**	**Components**	**Technicians**	**Duration**	**Status**	**Maintained**
HCV: 6											
1	321 39 93	Eicher-6 wheeler	31-Jan-26	2	WORKSHOP	Foreign object lodged between dual tyres was safely removed		Manish	10 min	Completed	29-Jan-26
2	321 39 110	Eicher-10 wheeler	31-Jan-26	0	WORKSHOP	Propeller shaft bolts replaced	Shaft bolts	Arjun, Manish	30 min	Completed	28-Jan-26
3	321 39 111	Eicher-6 wheeler	31-Jan-26	0	WORKSHOP	FR suspension bkts welded and repaired and greased	Grease, Electrodes	Binod, Raymond	30 min	Completed	30-Jan-26
4	321 39 107	Eicher-10 wheeler	31-Jan-26	0	WORKSHOP	Air pressure pipe defective; replaced, twice in a day	Air pressure pipe	Arjun, Manish	1 hr	Completed	28-Jan-26
5	GA2KHA9333	NOC	31-Jan-26	0	WORKSHOP	Hanger replaced	Hanger	Sagar, Binod	4 hrs	Completed	14-Jan-26
6	321 39 132	Tata-10 wheeler	30-Dec-25	32	WORKSHOP	Propeller Shaft Sleeve Yoke and Pinion Flange failure. Drivetrain disconnected; vehicle unable to move. Replacement of slip-joint assembly; under maintenance		Arjun, Manish	1.5 hrs	Pending	26-Dec-25
Shotcrete Machine: 1											
7	321 19 75	Robert Shotcrete-Putzmeister	31-Jan-26	0	TRT	Relay unit replaced	Relay	Ram	1 hr	Completed	11-Jan-26
Excavator: 2											
8	321 45 21	Komatsu Excavator PC-210	31-Jan-26	0	ADIT	Nitrogen gas replenished	Nitrogen gas	Kedar, Sagar	1 hr	Completed	29-Jan-26
9	321 45 43	CAT Excavator 323D3	31-Jan-26	0	CRUSHER	Repaired bucket replaced and greased	Repaired bucket	Sagar, Binod	30 min	Completed	29-Jan-26
Light vehicle: 1											
10	321 44 38	Mahindra Bolero	31-Jan-26	0	WORKSHOP	Gear Oil top up by 4L	Gear Oil	Manish	20 min	Completed	24-Jan-26
Tractor: 2											
11	321 38 28	Tractor Arjun- Mahendra	31-Jan-26	0	WORKSHOP	Fuel tanker leakage issue resolved and one new tyre replaced and 1 punctured tyre repaired	Tyre, Electrodes	Anil, Raymond, Arjun, Manish	2.5 hrs	Completed	13-Jan-26
12	321 38 31	Tractor Arjun- Mahendra	31-Jan-26	0	WORKSHOP	2 new tyres with tube replaced	Tyres with tube	Arjun, Manish	1 hr	Completed	13-Jan-26
Wheel Loader: 1											
13	321 44 47	Wheel Loader-Lonking	31-Jan-26	0	WORKSHOP	High temperature sign issue attended, air filter cleaner element remaintained		Bahmukunda, Arjun	45 min	Completed	22-Jan-26
Rock Hammer Breaker: 1											
14	321 17 07	Breaker hammer	31-Jan-26	0	WORKSHOP	Breaker piston bush replaced		Kedar	2.5 hrs	Pending	-